Mowbray Chapel

Chestertown

Mowbray Chapel, a long-abandoned building is in ruinous condition, is one of the few true Greek Revival structures in Kent County. Although simple in design it has a well-proportioned gabled facade, a generous and elegant interior space and handsome interior trim. Located on Quaker Neck Road 2 miles southwest of Johnsontown Road, it is a onestory structure with its main entry in the northern gable and a projecting alter at its southern gable. Three bays in length, its single interior room is lighted by very large 12 over 12 double hung windows. The Chapel was constructed by the Methodist Episcopol Church as a companion to Bond Chapel (K-28) nearby. Following a fire in 1889, it was rebuilt in 1890. Along with the Cliffs School (K-309), Mowbray Chapel served a focus for social activity for the community, Cliffs, and nearby farms.

# Maryland Historical Trust State Historic Sites Inventory Form

Magi No. 1502475608

DOE \_\_yes \_\_no

1. Nam	e (indicate pr	eferred name)		
historic Mowb	ray Chapel, Walton	Chapel		
and/or common	Mowbray Chapel			
2. Loca				
street & number	S.E. side Quaker Quaker Neck Road(	Neck Rd. 2 miles SW	of Johnsontown Rd.	not for publication
city, town	Chestertown,	-X vicinity of	congressional district	1st
state	Mary1and 21620	county	Kent	
3. Clas	sification		•	
Category  district _X_ building(s) structure site object	Ownership public private both Public Acquisition in process being considered not_applicable	Status occupied unoccupied work in progress AccessibleX_ yes: restricted yes: unrestricted no	Present Use agriculture commercial educational entertainment government industrial military	museum park private residence religious scientific transportation other:
4. Own	er of Prope	rty (give names an	nd mailing addresse	s of <u>all</u> owners)
name River	Farms Inc			
	76 Eastern Loop Ro		telephone no	o.:
city, town	Staten Island	state	and zip code New Y	ork. 10304
5. Loca	ation of Leg	al Description	on	
courthouse, regi	stry of deeds, etc. Kent	County Court House		liber EHP 114
street & number		UTA		folio 116
city, town Cho	estertown		state <sub>M</sub>	arvland 21620
6. Rep	resentation	in Existing	Historical Surv	
title				
'ব <u>t</u> e			federal stat	e county loca
depository for su	urvey records			
city, town			state	

7. Description			Survey No. K-247
Condition excellent good fair	X deteriorated ruins unexposed	Check one unaltered altered	Check one  X original site moved date of move

Prepare both a summary paragraph and a general description of the resource and its various elements as it exists today.

Mowbray Chapel is a one-story brick structure with its main entry in the northern gable and a projecting altar at its southern gable. Three bays in length, its single interior room is lighted by very large 12 over 12 double-hung windows.

_ 1400- _ 1500- 1600- 1700- _X_ 1800-	storic archeology-prehistoric -1499 archeology-historic -1599 agriculture -1699x architecture	community planning conservation economics	law literature military music t philosophy	science sculpture social/ humanitarian theater
Specific	dates	Builder/Architect		
check:	Applicable Criteria:A and/or Applicable Exception:A	<del></del>	EFG	
	Level of Significance: _	_nationalstate	local	
Prepare support	both a summary paragraph	of significance and	a general statement o	of history and

Survey No. K-247

8. Significance

Mowbray Chapel, a long-abandoned building in ruinous condition, is one of the few true Greek Revival structures in Kent County. Although simple in design it has a well- proportioned gable facade, a generous and elegant interior space, and handsome interior trim. The Chapel was constructed by the Methodist Episcopol Church as a companion to the Bond Chapel (K280) nearby. Following a fire in 1889, it was rebuilt in 1890. Along with the Cliffs School (K-309) nearby, it served a focus for social activity for the nearby community called Cliffs (or Cliffs City) and nearby farms.

## 9. Major Bibliographical References

Survey No. K-247

10. Geo	graphical Data		
Quadrangle name	do NOT complete UTM refe		Quadrangle scale
A Zone Easting		B Zone	Easting Northing
C		D	
Verbal boundary	description and justification		i
List all states an	nd counties for properties over	lapping state or co	code
state ·	code	county	code
11. Forn	n Prepared By		
	a L. Fritz, Surveyor ty Commissioners of Kent	County	
organization Hist	orical Society of Kent Co	ounty da	nte April 29, 1981
	The Court House Church Alley		778-4600 lephone 778-3499
city or town	Chestertown	st	ate Maryland 21620

The Maryland Historic Sites Inventory was officially created by an Act of the Maryland Legislature to be found in the Annotated Code of Maryland, Article 41, Section 181 KA, 1974 supplement.

The survey and inventory are being prepared for information and record purposes only and do not constitute any infringement of individual property rights.

return to:

Maryland Historical Trust

Shaw House 21 State Circle

Annapolis, Maryland 21401

(301) 269-2438

### CONTINUATION SHEET

7.1 DESCRIPTION (continued)

### BUILDING FORM AND MATERIAL

1. Size

Main Section: 1 story, 1 bay wide, 3 bays deep

2. Plan type

Main Section: Rectangular room (see drawing) with projecting chancel at southern

gable.

Roof type

Main Section: Shallow gable with shed at chancel.

4. Chimney(s)

Location(s): 2, between 1st and 2nd bay on each side

Materials: Parged brick, short, used for stoves

Decorative elements: Tall, handsome, yellowish clay, chimney pots.

Material/Walls

Main Section: Brick, ransom running, small bright orange bricks with untooled joints

Bays and corners demarcated with plain brick pilasters; capitals are

boow

Material/Roofs

Main Section: wood shingle

7. Material/Foundation

Main Section: Brick (no water table)

8. Age

Main Section: Circa 1865; rebuilt 1890, Mowbray Chapel closely resembles other Greek

Revival buildings in Kent County, all built in the 1850's. Bond Chapel (K-280) is a sister church built in 1851. A marble corner stone at

Mowbray Chapel, probably with a date has been defaced.

9. Style- Vernacular Greek Revival. Although smaller, this building is probably similar to Bond Chapel before its later alterations.

#### BUILDING ELEMENTS AND DETAILS

1. Doors

Main Entry: Main entry centered in northern gable; its original 44" double doors have been removed. It retains its bold architrave trim with 11-light transom,

molded transom bar and paneled 3-light side lights. Greek o.g. % = 1 bevel moldings are used on both interior % = 1 major exterior trim. Granite sill

and step.

Secondary Entries: Southwest rear corner. A single 4-panel door with sand stone step.

See drawing

F- - M

2. Windows

Main Section: double hung, very large, splayed jambs inside.

Lights - 12/12 with clear glass

#### CONTINUATION SHEET

## 7.2 DESCRIPTION (continued)

details - Splayed gauged brick flat arches outside; large plain wooden sills, large bead frame. Interior trim wider than that illustrated below but same backband and bead used.

shutters - Hinges remain throughout. Narrow louvered shutters on 4/4 windows at sides of chancel.

NOTE: Windows into crawl space have nice cast iron grilles

- 3. Dormers: None
- 4. Roof Details

Main Section: front gable: Cornice and 30" return have flattish composite crown and bed moldings and an 8" fascia attached to the top of the brick walls Rear Gable: is simpler with a molded verge board. The chancel roof is finished with a very large (ca8") cyma reversa, an unusual molding.

- 5. Porches None
- 6. Color: Current Trim- pale ochre Brick reddish orange
  Historic Trim appears to be original.1924-25--last recorded date of painting
  entire interior and exterior trim.
- 7. Other: This is a very beautiful, gracefully proportioned building which is one of the least altered Greek Revival Churches in Kent County.

## **INTERIOR DESCRIPTION**

- 1. Plan type- A single room with a recessed, raised altar with a chancel rail.
- 2. Major Stair- None (altar) A handsome architrave or Greek revival moldings about 11" wide at jambs; top of altar opening 10'9" from floor
- 3. Major Mantles The building was heated with a stove. Chancel Rail: Turned Balusters
- 4. Major Trim

Windows/doors - Very bold interior window & down trim. See illustration. Windows have splayed jambs.

Baseboards - A Greek o.g.  $\xi$  bevel molding at the base of the wainscating Cornices - A greek o.g. and bevel about  $2\frac{1}{2}$ "in height.

Chair Rails - 1 wainscoting- simple board/ with Greek o.g. molding; vertical beaded boarding.

- 5. Major Doors 4 panel doors with 1-3/4" Greek og and bevel panel moldings.
- 6. Floors Medium width random yellow pine, unfinished
- 7. Walls/ceiling finishes plaster walls and yellow pine beaded board ceiling (the original Walton Chapel was papered in 1889)

### OUTBUILDINGS/SITE DESCRIPTION

- 1. Major outbuildings:
  - A. Original use kitchen, church hall Form gable roofed Material Frame, collapsing

#### CONTINUATION SHEET

.3 DESCRIPTION (continued)

Construction system - modern construction system

- 2. Site description Set near the south side of Quaker Neck Road, the Chapel is surrounded by woodlands. It faces an open field and has a view of?
- 3. Views to/from site -

#### USE OF BUILDING

1. Current: vacant
Historic: church

### HISTORY OF BUILDING/PAST OWNERSHIP

The parcel where Mowbray Chapel stands was purchased by the board of trustees of the M. E. Church on February 24, 1864 (JKH 4/218) for the purpose of erecting a "house or place of worship". Presumably a building was constructed soon thereafter. Fragmentary information about the history of Mowbray Chapel is now in the possession of Bond Chapel, Pomona, which was part of the same charge as Mowbray Chapel. Originally called Walton Chapel, the church faced an uncertain future in 1882, when there was no longer a congregation. Later in the 80's however, services resumed though in 1889, the Sunday School was disbanded. On October 6, 1889, the church was "destroyed by fire" during a revival, and services hereafter were held at the Cliffs School (K-309). Under the leadership of the energetic minister appointed to the charge in March 1889, W.R. Mowbray, Hynson's Chapel (at Baker's Lane and Langford - Sandy Bottom Rd.), unused for at least ten years, was granted to the Walton congregation. It is not known to what extent Walton Chapel was damaged or destroyed or what elements used in the rebuilding besides bricks came from Hynson Chapel. It is likely that destruction was total except perhaps for the foundation. The new church may have been a reconstruction of the old one, which may explain the Greek Revival style at such a late date. Or it may have followed the form of Bond Chapel (K-280) or Hynson's Chapel, whose style is now not known.

Work began in 1890 on the new church, with the father of the minister as one of the mason constructors. The pastor himself did the lathing and plaster work. The total cash outlay was \$970.00; much material and labor was donated. Dedicated July 20, 1890, the church was then named in honor of the minister, W.R. Mowbray. In 1893, church records note, a stable was fully paid for. This may be the structure in ruinous condition to the Southeast of the church, but most likely it was the Church hall, used especially for festivals and suppers.

The church was declared abandoned and the land sold in 1963 (EHP 3/224).

1. STATE Maryland Kent COUNTY

TOWN Chestertown VICINITY Quaker Neck STREET NO. Md. 289, 8 miles south of Chestertown

ORIGINAL OWNER ORIGINAL USE religious percal 150 PRESENT OWNER ROY RUNNER vacaht PRESENT USE prick WALL CONSTRUCTION NO. OF STORIES 1

HISTORIC AMERICAN BUILDINGS SURVEY INVENTORY K-247

2. NAME Mowbray M.E. Chapel

1890 DATE OR PERIOD STYLE Greek Revival ARCHITECT BUILDER

3. FOR LIBRARY OF CONGRESS USE

4. NOTABLE FEATURES, HISTORICAL SIGNIFICANCE AND DESCRIPTION

OPEN TO PUBLIC DO

Mowbray Chapel is a small deserted brick building which had its corner stone laid in 1890. It is three bays deep and has a central door on its gable with double doors, transon and sidelights. There are pilasters at the corners and between the windows on the sides, also of brick. On the gable opposite the door is a leanto with windows in the sides for the sanctuary. There is a single door on the south side of the east gable.

Above the windows are flat brick arches. At ground level are vents with cast iron grates covering the openings. The entire structure is laid in common There is a very heavy wood facia at the cornice and there are returns above the corner pilasters.

Most of the interior furniture is still in place but in poor condition. In the center of each side wall is a brick chimney which is capped with a chimney pot after it pierces the roof.

fair poor Exterior Endangered YSS 5. PHYSICAL CONDITION OF STRUCTURE Interior





6. LOCATION MAP (Plan Optional)

8. PUBLISHED SOURCES (Author, Title, Pages) INTERVIEWS, RECORDS, PHOTOS, ETC.

7. PHOTOGRAPH

9. NAME, ADDRESS AND TITLE OF RECORDER Michael Bourne

Oct. 12, 1968

DATE OF RECORD

K\_ 241

APHS MAY BE ADDED ON SHEET OF SAME

SUPPLEMENTAL INFORMATION AND PHOTO

Form 10-445

1. STATE Mary land COUNTY Kent TOWN Chrotartonn

NO. OF STORIES

VICINITY Quality Week

STREET NO. Rt 289 - S. / Chestartown.

2. NAME Mowbray M.E. Chapel

HISTORIC AMERICAN BUILDINGS SURVEY

INVENTORY

DATE OR PERIOD 1890 Greek Revival STYLE ARCHITECT BUILDER

3. FOR LIBRARY OF CONGRESS USE

ORIGINAL OWNER Religious ORIGINAL USE PRESENT OWNER Vacant PRESENT USE WALL CONSTRUCTION brock

4. NOTABLE FEATURES, HISTORICAL SIGNIFICANCE AND DESCRIPTION

OPEN TO PUBLIC

Monterey Chapel is a small desorted brich building which had its corner stone lacil in 1590. It is 3 says deep and he a central door on its goode with double doors, transom + sidelyhts. There are pilotos at the corners of between the winden on den sids. On the gade appointe the door is a learly with wind in the sides for the spanetury. sigh door on the guble

Here are plat orches are see windows and Went's at grand level wife cost iron grates coming them. Her but is the is heavy wood facia, last - comme band throughout. osahed a returns at the piloters.

most y the inter furnit : in place but : poor Condition. Du cach think: a ching notice the havin a chim pot.

5. PHYSICAL CONDITION OF STRUCTURE Endangered 425 DOOR Exterior Interior

6. LOCATION MAP (Plan Optional)

7. PHOTOGRAPH

8. PUBLISHED SOURCES (Author, Title, Pages) INTERVIEWS, RECORDS, PHOTOS, ETC.

9. NAME, ADDRESS AND TITLE OF RECORDER Michael (Source


DATE OF RECORD 12,1968

DOOR TRIM

INTERIOR MOWBRAY CHAPEL

K-247

## QUAKER NECK ROAD




ERICK WALL THICKNEES- 14"

NO SCALE
HUFEITZ 4/8/

MOWERRY CHAPEL

K-247





K-247 Mowbray Methodist Chapel Rt. 289, Quaker Neck, near Chestertown M. Q. Fallaw - 3/29/86 View to east



K-247 Mowbray Methodist Chapel Rt. 289, Quaker Neck, near Chestertown M. Q. Fallaw - 3/29/86 View to southeast